





Bedford Plant Corrective Action
Public Information Session
February 13, 2024





Project Overview: Key Milestones





Work Completed Since September 2022 Meeting

1. Continued to operate GWTP to treat PCB-impacted remediation waters
2. Continued to recover subsurface oil for mass removal of PCBs from the environment
3. Maintained landfill cover system
4. Continued groundwater monitoring
5. Completed Pilot Trench performance monitoring
6. Completed oil recovery evaluation
7. Updated project website
8. Submitted Annual Vault Report
9. Submitted Pilot Trench Performance Monitoring Report
10. Contracted with Severson Environmental Services to construct Phase II Trench
11. Began construction of the Phase II Trench in January 2023 (now, substantially complete)
12. Continued working the USEPA and IDEM on Corrective Measures Proposal and Long Term Operation, Monitoring, and Maintenance Plan


Phase II Trench Construction



Phase II Trench Construction



Phase II Trench Construction



Phase II Trench Construction




Phase II Trench Construction




Phase II Trench Construction





Site Model



Spring 018 Berm Removal



Confluence Repair



Project Overview: Future Key Milestones

